



Compliance Order No. 003/2015

## COMPLIANCE ORDER

(Under Section 40 of the Electricity Act, 1999 Chapter 145 Laws of Uganda)

The Electricity Regulatory Authority ('the Authority') is of the opinion that **Ferdsult Engineering Services Limited (FESL)** is contravening the terms and conditions of its license and requirements under the Electricity Act, 1999 ('the Act') and accordingly directs **Ferdsult Engineering Services Limited** to comply with the Act and the terms and conditions of its licenses Nos. 066, 086 and 087 as follows:-

1. **Ferdsult Engineering Services Limited** is in contravention of the provisions of its Licences and the Act by failing to comply with Condition 8.1.12 of license No. 066, Condition 7.1.10 of license No. 086 and Condition 7.1.10 of license No. 087 and Section 72 of the Act;
2. The acts and omission which in the opinion of the Authority constitute the contravention and breach of the license terms and conditions cited above and Sections 72 and 48(3) of the Act are as follows:-
  - 2.1 Failure to prepare and submit to the Authority a report covering the performance levels registered in respect of the Quality of Service Standards within fifteen (15) days from the end of the First Quarter of 2015.
3. **Ferdsult Engineering Services Limited** is directed and ordered to rectify the contravention of the License and the Act within a period of thirty (30) days from the date of this Compliance Order, and;
4. **Ferdsult Engineering Services Limited** or directly affected parties may make representations and objections in respect of this Compliance Order not later than twenty (20) days from the date of receipt of this Compliance Order.

Dated this.....<sup>13<sup>th</sup></sup>.....day of August, 2015

CHIEF EXECUTIVE OFFICER

